

COSHH Assessment Record

MATERIAL	Rema Tip Top Retread Tyre Building Solution – A5052
----------	---

LOCATION	Site / Van Storage
----------	--------------------

HEALTH RISKS	Harmful / Highly Flammable / Environment
--------------	--

HAZARDOUS CONTENTS	Mixed Hydrocarbon Isomer Solvent Blend
--------------------	--

ROUTES OF EXPOSURE	MAX EXPOSURE LIMIT
Skin <input checked="" type="checkbox"/> Eyes <input checked="" type="checkbox"/> Inhalation <input checked="" type="checkbox"/> Swallowing <input checked="" type="checkbox"/> Cuts <input checked="" type="checkbox"/>	8 hour TWA 225 ppm

DESCRIPTION OF HOW MATERIAL USED
Brush applied to conveyor belt joints etc.

SAFETY CONTROLS
Avoid direct sunlight, smoking, heat sources etc. Adequate ventilation (outdoor preferably), good personal hygiene. Keep away from food etc. Avoid eye and skin contact. Minimise quantity used.

PERSONAL PROTECTIVE EQUIPMENT
Goggles/Visor <input checked="" type="checkbox"/> Gloves <input checked="" type="checkbox"/> Overalls <input checked="" type="checkbox"/> Respirator <input checked="" type="checkbox"/> * if ventilation poor
Other (please specify) Safety glasses with side shields. Impervious clothing.

FIRST AID REQUIREMENTS	
Skin	Wash well with soap and water
Eyes	Water whilst lifting eyelids (10 mins.), medical attention
Ingestion	Rinse mouth, drink water, get medical attention
Inhalation	Remove to fresh air, get medical help

FIRE PRECAUTIONS	STORAGE REQUIREMENTS
Extinguisher: Foam, CO ₂ , dry chemicals sand, earth or water fog. Avoid static discharge and oxidising agents.	Keep container tightly closed in a cool, dry, well ventilated space. Dispose after 3 months. Clean empty containers thoroughly.

IN THE EVENT OF SPILLAGE
Do not flush into surface water, drains, sewers. Shovel into a suitable container for disposal. Obtain services of a waste disposal contractor.

SIGNED	DATE

